



REINFORCED MASONRY CHIMNEYS: Fracture Above Roof Line




DETAIL 1
Concrete Bond Beam



DETAIL 2: Roof Anchorage
Concrete Bond Beam Anchorage into Building




CITY OF BURBANK
COMMUNITY DEVELOPMENT DEPARTMENT
BUILDING DIVISION





DETAIL 2: Floor Anchorage
Concrete Bond Beam Anchorage into Building

Single Brace Required if Chimney Extends 4'-0" or More over Roof Line.



Double Brace Required if Chimney Extends 6'-0" or More over Roof Line



DETAIL 3:
Roof Brace