


## Masonry Chimney Damaged Above Roof Line - Wood Framing




Note: Unreinforced Masonry Chimneys Shall be Removed Down to the Throat

Warning: Install only a Properly Listed Residential "Type HT" Chimney on Wood Burning Fireplaces. Any Other Type May Create a Potential Fire or Safety Hazard.

### Section B Replacement of Damaged Masonry Firebox and Chimney with New Masonry Firebox and Factory-Built Metal Chimney

## Masonry Chimney Damaged Above Roof Line - Steel Studs



Note: Unreinforced Masonry Chimneys Shall be Removed Down to the Throat

Warning: Install only a Properly Listed Residential "Type HT" Chimney on Wood Burning Fireplaces. Any Other Type May Create a Potential Fire or Safety Hazard.

### Section B Replacement of Damaged Masonry Firebox and Chimney with New Masonry Firebox and Factory-Built Metal Chimney



**CITY OF BURBANK**  
**COMMUNITY DEVELOPMENT DEPARTMENT**  
**BUILDING DIVISION**